

S  
A  
F  
E  
T  
Y  
  
A  
L  
E  
R  
T  
  
S  
A  
F  
E  
T  
Y  
  
A  
L  
A  
R  
T



**SAFETY ALERT**

**SAFETY ALERT**



# **FIRE SAFETY**

## **Fake Smoke Detectors Have Been Found On KAF**

**The Garrison Safety Office, US Billeting Office and DynCorp will initiate 100% inspections and coordinate replacements beginning immediately for all LOGCAP O&M Facilities. Facilities not covered by LOGCAP O&M must be inspected by the occupants. Any fake detectors identified must be replaced.**

The fake smoke detectors look like the one pictured below. The alarm will sound when the test button is activated but the detector will not alarm in the presence of smoke or heat. Remove the detector from its mount by twisting clockwise and pulling down. The fake smoke detectors all have the Serial ID 100223. One or both of the stickers may be missing from the back of the detector. The manufacturer listed on the smaller sticker is Yuyao Lixin Electronics Co Ltd.

**If you find one of these fake detectors and are not covered by LOGCAP O&M or US Billeting, contact the Garrison Safety Office at DSN 318-421-5929 or the COMKAF Fire Safety Office at NSN 685-1112 or DSN 98-685-1112 for guidance on exchanging the fake smoke detectors.**



**US Forces Base Operating Support Integrator (BOS-I) Safety Office**

**DSN: 318-421-5929**

**SAFETY ALERT**

**SAFETY ALERT**

S  
A  
F  
E  
T  
Y  
  
A  
L  
E  
R  
T  
  
S  
A  
F  
E  
T  
Y  
  
A  
L  
A  
R  
T